

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

- | | |
|--|--|
| 1. Name of the School :- | Maharishi Vidya Mandir |
| 2. Location :- | National Highway No- 6 Ashok Nagar Fulmogra
Bhandara (Maharastra) |
| 3. Plot Area: - | 87120 Sqft. |
| 4. Plinth Area: - | 15989 Sqft. |
| 5. Number of Storey's :- | G+3 , G+4 |
| 6. Year of Construction of Building: - | 2015 |

7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given

- (a) Name of the Engineer with qualification: - Sh. Chandresh Jain (Diploma Civil Engineering)
- (b) Address of Engineer: - E-7/760 Arera Colony Bhopal (M.P.)
- (c) Set of Structural drawings used in the construction, if available: - Available
- (d) Name & address of Architect with qualification: - Sh. Anjan Nandy (B. Arch)
E-8/73 Akash Ganga Colony Bhopal (M.P.)

8. Whether the building has been constructed for the purpose

- (a) School :- Yes
- (b) Residential Purpose and converted for use as a School: - No

9. Materials used for roofs

- (a) R.C.C. Slabs/R.B.C. Slabs: - Yes
- (b) R.S. Joist & Battons: - No
- (c) Wooden joists & Battons:- No

10. Materials used for walls

- (a) Mud Mortar:- No
- (b) Cement Mortar:- Yes
- (c) Lime Mortar:- No

11. Flooring

- (a) Conglomerate:- No
- (b) Terrazo:- Yes
- (c) Brick Paving:- No

12. A detailed drawing indicating dimensions of the rooms Along with size and location of doors and windows

(Attached)



Principal
Mrs. Shruti Ohale

PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 23.06.2021..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used)
10 years. (if proper maintenance.)

Sub Divisional Engineer

Bhandara.
23.06.2021.


Executive Engineer
Public Work Division
Zilla Parishad Bhandara.


V.Y. NIKHAR
B.E.CIVIL, MIE, FIV.
Chartered Engineer & Approved Valuer,
3rd Floor, Nikhar Bhawan, opp. Tukdoji Putla,
Main Road, Bhandara - 441904

V. Y. NIKHAR

B.E. Civil, MIE, FIV.
Chartered Engineer & Approved Valuer
Regd. No. 52/90

॥ Jai Lakshmi ॥

3rd Floor, Nikhar Bhavan
Opp. Tukdoji Putla
Main Road, Bhandara - 441 904.
☎ 07184-254917

PART - II

(To be filed by the S.D.E.)

- a) **I have visited the above mentioned school on dated 23.06.2021**
And have visually inspected in from all angles of safety and find it fit normal use a School building.
- b) In case any addition/ alteration or expansion and modifications to this building is to be carried out, the same be carried out the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of wall/ foundation or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto 40 years. (if proper maintenance)

Place:- Bhandara

Date :- 23.06.2021


V.Y. NIKHAR
B.E.CIVIL, MIE, FIV.
Chartered Engineer & Approved Valuer,
3rd Floor, Nikhar Bhawan, opp. Tukdoji Putla,
Main Road, Bhandara - 441904